## **Escomb Primary School**



**Accessibility Plan** 

### **Table of Contents**

#### **Section 1: Starting Points**

- Objectives
- Pupil Data
- Consultation Group


# Section 2: The main priorities in the school's plan

- Improving the physical environment
- Increasing access to the curriculum
- Providing information in different formats
- Additional Information

#### Section 3: Making it Happen

- Management
- Circulation

#### **Annexes/Appendices**




Escomb Primary School has high ambitions for its pupils with disabilities and will aim to provide the correct environment for them to participate and achieve in every aspect of school life. The school also intends to increase accessibility for staff and members of the public with disabilities. Childhood is a special period in our lives and it is the time in which we learn most. In developing the partnership between home and school we can help to make it pleasurable and fulfilling for our children. We hope that they all will achieve their full potential irrespective of race, creed, gender or ability

As part of our anticipatory duty we will examine the data we hold on our pupils to identify pupils with disabilities who attend the school. We will also take into consideration any advanced information that is made available. For example, from an earlier key stage or from a prospective pupil with a disability that is likely to attend the school. In the event of a child entering the school with a disability that we were not aware of prior to admission we will endeavour to make suitable arrangements and adaptations to ensure that the child is best equipped to access as much of school life as possible.

In order to ensure that we take into consideration a wide range of views regarding accessibility issues in the school we intend to form a planning group that will consist:

- Headteacher
- Deputy Headteacher
- Chair of Governors
- SFNCo
- A suitable pupil, parent or member of the local community who has some form of disability



#### The main priorities in the School's Plan

We are aware of the three duties that cover the provision of education

- The disability discrimination duties in Part 4 of the DDA
- The planning duties in Part 4 of the DDA
- The Special Educational Needs (SEND) duties


And we understand that these three sets of duties are combined to provide the statutory framework that underpins equality of opportunity for pupils with disabilities in accessing school education.

We are also aware that the duty not to treat a pupil with disabilities less favourably and the duty to make reasonable adjustment are the two core duties that lie at the heart of the disability discrimination provisions in education. In compiling its Accessibility Plan the school will utilise the "support package" provided via the schools extranet. These resources will be used in conjunction with the database software that highlights issues relating to all three areas from the planning duties:

- Increasing access to the curriculum;
- Improving the physical environment;
- Providing information in different formats
- a. Following the schools physical audit we will take the issues of non-compliance detailed in our database and address each item individually and put forward our action plan, timescale and funding methods.
- b. Using the curriculum section and the database we will answer all questions and again propose our action plan, timeframe and funding to address any areas of shortfall.
- c. Again using the information section and the database we will answer all questions and again propose our action plan, timeframe and funding to address any areas of shortfall.

We will also use the additional information section within the database in order to cover any issues that are not detailed within the audit, curriculum and information sections.

Evacuation Plan We will develop and implement an evacuation of people with disabilities plan using the guidance and instructions from British Standards (BS 5588-12:2004) (Link) (See Annex 2).



#### Accessibility Action Plan - Access Audit

| A.1.7 Is the route free of kerbs?   |
|---|
| Priority  |
| 7 - Outside curtilage of site   |
| Location  |
| Block 0 - Hallimond Road  |
| Comments  |
| Drop kerbs provided at far side bus stop, consider tactile and crossing   |
| Compliant: No Timescale: Not Specified Funding: Not Specified             |
| Action / Future Plan  |
|   |
| A.1.8 Is the surface smooth and slip resistant?                           |
| Priority  |
| 7 - Outside curtilage of site   |
| Location  |
| Block 0 - Hallimond Road  |
| Comments  |
| Tarmac defective in areas, carry out repairs as part of maintenance works |
| Compliant: No Timescale: Not Specified Funding: Not Specified             |
| Action / Future Plan  |
|   |
| A.1.9 Is the route wide enough?   |
| Priority  |
| 7 - Outside curtilage of site   |
| Location  |
| Block 0 - Hallimond Road  |

| Comments  |  |
|---|--|
| Safety barriers at pedestrian gates reduce passage to 960 and 1170mm wide |  |
| Compliant: No Timescale: Not Specified Funding: Not Specified             |  |
| Action / Future Plan  |  |
|   |  |
| A.2.3 Is there a dropping off area?                                       |  |
| Priority  |  |
| 3 - Part of Maintenance work  |  |
| Location  |  |
| Block 0 - Off Hallimond Road  |  |
| Comments  |  |
| Consider provision and mark out area                                      |  |
| Compliant: No Timescale: Ongoing Funding: Other Funding                   |  |
| Action / Future Plan  |  |
| Asked for in School Travel Plan   |  |

| Priority  3 - Part of Maintenance work  Location  Block 0 - Off Hallimond Road  Comments  As above  Compliant: Yes Timescale: Ongoing Funding: Other Funding  Action / Future Plan | Is there a designated area for coaches/minibuses to load and unload? |  |
|--|--|--|
| Location  Block 0 - Off Hallimond Road  Comments  As above  Compliant: Yes Timescale: Ongoing Funding: Other Funding   | ity  |  |
| Block 0 - Off Hallimond Road  Comments  As above  Compliant: Yes Timescale: Ongoing Funding: Other Funding   | irt of Maintenance work  |  |
| Comments  As above  Compliant: Yes Timescale: Ongoing Funding: Other Funding   | tion   |  |
| As above  Compliant: Yes Timescale: Ongoing Funding: Other Funding   | 0 - Off Hallimond Road   |  |
| Compliant: Yes Timescale: Ongoing Funding: Other Funding   | nents  |  |
|  | ove  |  |
| Action / Future Plan   | oliant: Yes Timescale: Ongoing Funding: Other Funding                |  |
|  | n / Future Plan  |  |
| Already present  | dy present   |  |

**A.3.2** Are there designated car parking spaces for people with disabilities?

| Priority   |
|--|
| 2 - As soon as possible  |
| Location   |
| Block 0 - RHS of Block 1   |
| Comments   |
| Consider provision of at least one bay with signage on tarmac area |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital       |
| Action / Future Plan   |
| To be arranged once tarmac applied to school car park              |
|  |
| A.3.8 Is the car park surface suitable?                            |
| Priority   |
| 4 - Part of Refurbishment work                                     |
| Location   |
| Block 0 - RHS of Block 1   |
| Comments   |
| Type 1 to both car parks, consider tarmac                          |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital       |
| Action / Future Plan   |
| Provision of tarmac surface  |
|  |
| A.3.10 Is the car park lighting adequate?                          |
| Priority   |
| 3 - Part of Maintenance work                                       |
| Location   |
| Block 0 - RHS of Block 1   |
| Comments   |
| Consider lighting  |

Ξĺ

| Compliant: Yes Timescale: Ongoing Funding: Devolved Capital    |
|--|
| Action / Future Plan   |
| Additional lighting has been provided                          |
|  |
| B.1.3 Is the route level?                                      |
| Priority   |
| 4 - Part of Refurbishment work                                 |
| Location   |
| Block 0 - Adjacent rear elevation B1                           |
| Comments   |
| Ramped path, consider fitting handrails to both sides of path  |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital   |
| Action / Future Plan   |
| To be considered when funding is available                     |
|  |
| B.1.8 Is the route adequately lit?                             |
| Priority   |
| 3 - Part of Maintenance work                                   |
| Location   |
| Block 0 - Adjacent rear elevation B1                           |
| Comments   |
| Consider lighting  |
| Compliant: Yes Timescale: Ongoing Funding: Other Funding       |
| Action / Future Plan   |
| Outside light provided   |
|  |
| B.2.3 Does the ramp surface contrast with surrounding pavings? |
| Priority   |

| 2 - As soon as possible   |
|---|
| Location  |
| Block 0 - Adjacent elevation B1   |
| Comments  |
| Paint gradient on ramped path to contrast                                   |
| Compliant: No Timescale: Within 12 Months Funding: Other Funding            |
| Action / Future Plan  |
| To be painted appropriately   |
|   |
| B.2.5 Are the landings of adequate size with intermediate landings if long? |
| Priority  |
| 5 - When a specific need is identified                                      |
| Location  |
| Block 0 - Adjacent elevation B1   |

| Priority   |
|--|
| 5 - When a specific need is identified                       |
| Location   |
| Block 0 - Adjacent elevation B1                              |
| Comments   |
| Ramped path approx 6.9 m, no intermediate landing            |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital |
| Action / Future Plan   |
| To be considered when funding is available                   |
|  |

| B.2.9 Is the ramp adequately lit?                            |
|--|
| Priority   |
| 3 - Part of Maintenance work                                 |
| Location   |
| Block 0 - Adjacent elevation B1                              |
| Comments   |
| Consider lighting (3x lamps & standards)                     |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital |

| To be considered when funding is available - not normally used during the dark |  |
|--|--|
|  |  |
| B.2.11 Are the step treads long enough and all of the same length?             |  |
| Priority   |  |
| 5 - When a specific need is identified   |  |
| Location   |  |
| Block 0 - Adjacent elevation B1  |  |
| Comments   |  |
| 430-435mm  |  |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital                   |  |
| Action / Future Plan   |  |
| To be considered when funding is available                                     |  |
|  |  |
| B.2.11 Are the step treads long enough and all of the same length?             |  |
| Priority   |  |
| 5 - When a specific need is identified   |  |
| Location   |  |
| Block 0 - Adjacent Block 3   |  |
| Comments   |  |
| 310-315mm long   |  |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital                   |  |
| Action / Future Plan   |  |
| To be considered when funding is available                                     |  |
|  |  |
| B.2.11 Are the step treads long enough and all of the same length?             |  |
| Priority   |  |

Action / Future Plan

5 - When a specific need is identified

| Location   |
|--|
| Block 0 - In between blocks 2 and 3                          |
| Comments   |
| 460-480mm long   |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital |
| Action / Future Plan   |
| To be considered when funding is available                   |
|  |

| <b>3.2.12</b> Are the risers shallow enough and all of the same height? |  |
|---|--|
|   |  |
| Priority  |  |
| 5 - When a specific need is identified                                  |  |
| Location  |  |
| Block 0 - In between blocks 2 and 3                                     |  |
| Comments  |  |
| 135-145mm high  |  |
| Compliant: Yes Timescale: Not Specified Funding: Other Funding          |  |
| Action / Future Plan  |  |

| B.2.12 Are the risers shallow enough and all of the same height?                 |
|--|
| Priority   |
| 5 - When a specific need is identified   |
| Location   |
| Block 0 - Adjacent Block 3   |
| Comments   |
| 100-150mm high with projection up to 20mm, acceptable                            |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital                     |
| Action / Future Plan   |
| To be considered when funding is available                                       |
|  |
| B.2.13 Are the nosings readily identifiable and unlikely to create trip hazards? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 0 - In between blocks 2 and 3  |
| Comments   |
| Paint nosings  |
| Compliant: No Timescale: Within 12 Months Funding: Other Funding                 |
| Action / Future Plan   |
| To be painted appropriately  |
|  |
| B.2.13 Are the nosings readily identifiable and unlikely to create trip hazards? |
| Priority   |
| 2 - As soon as possible  |

Steps no longer present

Location

| Block 0 - Adjacent elevation B1  |
|--|
| Comments   |
| Paint nosings  |
| Compliant: No Timescale: Within 12 Months Funding: Other Funding                 |
| Action / Future Plan   |
| To be painted appropriately  |
|  |
| B.2.13 Are the nosings readily identifiable and unlikely to create trip hazards? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 0 - Adjacent Block 3   |
| Comments   |
| Paint nosings  |
| Compliant: No Timescale: Within 12 Months Funding: Other Funding                 |
| Action / Future Plan   |
| To be painted appropriately  |
|  |
| B.2.14 Are adequate handrails provided to both sides, including tapping rails?   |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 0 - Adjacent elevation B1  |

Comments

Action / Future Plan

Handrail to be fitted

Fit handrail to wall to match existing

Compliant: No Timescale: Within 12 Months Funding: Devolved Capital

| <b>B.2.15</b> Are visual and tactile warning signs provided at the top and bottom of steps? |
|---|
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 0 - Adjacent elevation B1   |
| Comments  |
| Provide   |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital                                |
| Action / Future Plan  |
| To be provided  |
|   |
| <b>B.2.15</b> Are visual and tactile warning signs provided at the top and bottom of steps? |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 0 - Adjacent Block 3  |
| Comments  |
| Provide   |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital                                |
| Action / Future Plan  |
| To be provided  |
|   |
| <b>B.2.15</b> Are visual and tactile warning signs provided at the top and bottom of steps? |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 0 - In between blocks 2 and 3   |

Comments

| Provide  |
|--|
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital |
| Action / Future Plan   |
| To be provided   |
| D 2.4.7 And the atoms adamy atoly 199                        |
| B.2.17 Are the steps adequately lit?                         |
| Priority   |
| 3 - Part of Maintenance work                                 |
| Location   |
| Block 0 - Adjacent Block 3                                   |
| Comments   |
| Included elsewhere   |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital |
| Action / Future Plan   |
| To be considered when funding becomes available              |
|  |
| B.2.17 Are the steps adequately lit?                         |
| Priority   |
| 3 - Part of Maintenance work                                 |
| Location   |
| Block 0 - In between blocks 2 and 3                          |
| Comments   |
| Included elsewhere   |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital |
| Action / Future Plan   |
| To be considered when funding becomes available              |
|  |

**B.2.17** Are the steps adequately lit?

| Priority  |
|---|
| 3 - Part of Maintenance work  |
| Location  |
| Block 0 - Adjacent elevation B1   |
| Comments  |
| Included above  |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital  |
| Action / Future Plan  |
| To be considered when funding becomes available   |
|   |
| C.1.1 Is there a ramp?  |
| Priority  |
| 4 - Part of Refurbishment work  |
| Location  |
| Block 1 - 0/018a Pupil entrance   |
| Comments  |
| Steps approx 200mm high, fit ramp   |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital  |
| Action / Future Plan  |
| Not used as access/egress currently for people needing a ramp; other doors used but to be considered when funding becomes available |
|   |
| C.1.2 Is the ramp accompanied by steps for ambulant disabled people?  |
| Priority  |
| 4 - Part of Refurbishment work  |
| Location  |
| Block 1 - 0/034 Principal entrance  |
| Comments  |
| Consider provision, ramp approx 250mm high  |

| Compliant: No Timescale: Not Specified Funding: Not Specified        |
|--|
| Action / Future Plan   |
|  |
| C.1.2 Is the ramp accompanied by steps for ambulant disabled people? |
| Priority   |
| 5 - When a specific need is identified                               |
| Location   |
| Block 1 - 0/034 Rear pupil entrance                                  |
| Comments   |
| Due to location  |
| Compliant: No Timescale: Not Specified Funding: Not Specified        |
| Action / Future Plan   |
|  |
| C.1.3 Does the ramp surface contrast with surrounding pavings?       |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/034 Principal entrance                                   |
| Comments   |
| Paint gradient of ramp to contrast                                   |
| Compliant: No Timescale: Within 12 Months Funding: Other Funding     |
| Action / Future Plan   |
| Gradient of ramp to be painted to contrast                           |
|  |
| C.1.3 Does the ramp surface contrast with surrounding pavings?       |
| Priority   |
| 2 - As soon as possible  |
| Location   |

| Block 1 - 0/034 Rear pupil entrance                              |
|--|
| Comments   |
| Paint gradient to provide contrast                               |
| Compliant: No Timescale: Within 12 Months Funding: Other Funding |
| Action / Future Plan   |
| Gradient of ramp to be painted to contrast                       |
| C.1.3 Does the ramp surface contrast with surrounding pavings?   |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/006c Infant entrance                                 |
| Comments   |
| Paint gradient to contrast                                       |
| Compliant: No Timescale: Within 12 Months Funding: Other Funding |
| Action / Future Plan   |
| Gradient of ramp to be painted to contrast                       |
| C.1.3 Does the ramp surface contrast with surrounding pavings?   |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/014a Rear pupil entrance                             |
| Comments   |
| Paint gradient to contrast                                       |
| Compliant: No Timescale: Within 12 Months Funding: Other Funding |
| Action / Future Plan   |
| Gradient of ramp to be painted to contrast                       |

| C.1.4 Is the ramp wide enough and is the gradient suitable?                   |
|---|
| Priority  |
| 5 - When a specific need is identified  |
| Location  |
| Block 1 - 0/014a Rear pupil entrance  |
| Comments  |
| 4 m x approx 375mm high giving it a gradient of approx 1:11                   |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital                  |
| Action / Future Plan  |
| To be considered for modification when funding becomes available              |
|   |
| C.1.5 Are the landings of adequate size with intermediate landings if long?   |
| Priority  |
| 5 - When a specific need is identifie   |
| Location  |
| Block 1 - 0/014a Rear pupil entrance  |
| Comments  |
| Approx only 910mm long  |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital                  |
| Action / Future Plan  |
| To be considered for rebuilding when funding becomes available                |
|   |
| C.1.6 Are adequate handrails provided to both sides, including tapping rails? |
| Priority  |
| 2 - As soon as possible   |
| Location  |

Block 1 - 0/014a Rear pupil entrance

Comments

| Reposition handrails to outside of ramp                        |
|--|
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital   |
| Action / Future Plan   |
| Tapping rails to be provided                                   |
|  |
| C.1.10 Are there external steps?                               |
| Priority   |
| 4 - Part of Refurbishment work                                 |
| Location   |
| Block 1 - 0/014a Rear pupil entrance                           |
| Comments   |
| Consider provision   |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| C.1.10 Are there external steps?                               |
| Priority   |
| 4 - Part of Refurbishment work                                 |
| Location   |
| Block 1 - 0/034 Principal entrance                             |
| Comments   |
| Included above   |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital   |
| Action / Future Plan   |
| To be considered for rebuilding when funding becomes available |
|  |
| C.1.11 Are the treads long enough and all of the same length?  |
| Priority   |

| 4 - Part of Refurbishment work  |
|---|
| Location  |
| Block 1 - 0/018a Pupil entrance                                       |
| Comments  |
| 290 and 620mm long, rebuild with ramp                                 |
| Compliant: No Timescale: 1-3 Years Funding: Access Initiative Funding |
| Action / Future Plan  |
| To be considered for rebuilding when funding becomes available        |
|   |
| C.1.12 Are the risers shallow enough and all of the same height?      |
| Priority  |
| 4 - Part of Refurbishment work  |
| Location  |
| Block 1 - 0/018a Pupil entrance                                       |
| Comments  |
| 60 and 125mm high, as above   |

| ings readily identifiable and unlikely to create trip hazards? |   |
|--|---|
|  |   |
| sible  |   |
|  |   |
| upil entrance  |   |
|  |   |
|  |   |
| os   | osings readily identifiable and unlikely to create trip hazards?  ossible  Pupil entrance |

Compliant: No Timescale: 1-3 Years Funding: Devolved Capital

To be considered for rebuilding when funding becomes available

Action / Future Plan

| T. L  |
|---|
| To be painted appropriately   |
|   |
| C.1.15 Are visual and tactile signs provided at the top and bottom of steps?          |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/018a Pupil entrance   |
| Comments  |
| Provide   |
| Compliant: No Timescale: Within 12 Months Funding: Devolved Capital                   |
| Action / Future Plan  |
| To be provided  |
| <u>L</u>  |
| C.1.16 Are the landings of adequate size with intermediate landings on a long flight? |
| Priority  |
| 4 - Part of Refurbishment work  |
| Location  |
| Block 1 - 0/018a Pupil entrance   |
| Comments  |
| Include with ramp   |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital                          |
| Action / Future Plan  |
| To be considered when funding becomes available                                       |
|   |
| C.1.17 Are the steps adequately lit?  |
| Priority  |
| 2 - As soon as possible   |
|   |

Action / Future Plan

| Location  |
|---|
| Block 1 - 0/018a Pupil entrance   |
| Comments  |
| Included elsewhere  |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital  |
| Action / Future Plan  |
| To be considered when funding becomes available   |
|   |
| <b>C.2.5</b> Do the entry phones and security systems allow use by people with sensory or mobility impairments? |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/034 Principal entrance  |
| Comments  |
| Door entry is acceptable, fit sign to highlight its position  |
| Compliant: No Timescale: Not Specified Funding: Not Specified   |
| Action / Future Plan  |
|   |
| <b>C.2.5</b> Do the entry phones and security systems allow use by people with sensory or mobility impairments? |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 3 - 0/004   |
| Comments  |
| Doorbell only, at a adequate height, fit sign   |
| Compliant: Yes Timescale: Not Specified Funding: Other Funding  |
| Action / Future Plan  |

| C.3.1 Is the opening of the main entrance door of an adequate width? |
|--|
| Priority   |
| 4 - Part of Refurbishment work                                       |
| Location   |
| Block 1 - 0/018a Pupil entrance                                      |
| Comments   |
| 620mm wide, replace with door and a half set once ramp is fitted     |
| Compliant: Yes Timescale: Not Specified Funding: Other Funding       |
| Action / Future Plan   |
| Both doors can be opened   |
|  |
| C.3.1 Is the opening of the main entrance door of an adequate width? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 2 - 0/002  |
| Comments   |
| 730mm wide, replace with door and a half set                         |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital         |
| Action / Future Plan   |
| To be considered when funding becomes available                      |
|  |
| C.3.1 Is the opening of the main entrance door of an adequate width? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
|  |

Completed

| Block 1 - 0/006c Infant entrance   |
|--|
| Comments   |
| 635mm wide, replace with door and a half set                               |
| Compliant: Yes Timescale: Not Specified Funding: Devolved Capital          |
| Action / Future Plan   |
| door changed both sides can now be opened                                  |
|  |
| C.3.5 Is the door handle/control at a suitable height and easy to operate? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 2 - 0/002  |
| Comments   |
| Included above   |
| Compliant: No Timescale: Not Specified Funding: Not Specified              |
| Action / Future Plan   |
|  |
| C.3.5 Is the door handle/control at a suitable height and easy to operate? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 3 - 0/004 Yr 4 and 5   |
| Comments   |
| Replace 2No  |
| Compliant: No Timescale: Not Specified Funding: Not Specified              |
| Action / Future Plan   |
|  |

**C.3.5** Is the door handle/control at a suitable height and easy to operate?

| Priority   |
|--|
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/018a Pupil entrance  |
| Comments   |
| Replace  |
| Compliant: No Timescale: Not Specified Funding: Not Specified              |
| Action / Future Plan   |
|  |
| C.3.5 Is the door handle/control at a suitable height and easy to operate? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/014a Rear pupil entrance                                       |
| Comments   |
| Replace  |
| Compliant: No Timescale: Not Specified Funding: Not Specified              |
| Action / Future Plan   |
|  |
| C.3.5 Is the door handle/control at a suitable height and easy to operate? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/006c Infant entrance   |
| Comments   |
| Included with new door set   |
| Compliant: No Timescale: Not Specified Funding: Not Specified              |
| Action / Future Plan   |

| C.3.5 Is the door handle/control at a suitable height and easy to operate? |
|--|
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/034 Rear pupil entrance  |
| Comments   |
| Replace  |
| Compliant: No Timescale: Not Specified Funding: Not Specified              |
| Action / Future Plan   |
|  |
|  |
| C.3.8 Is the threshold level or flush with surface flooring?               |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 2 - 0/002  |
| Comments   |
| Approx 40mm high, provide graded threshold                                 |
| Compliant: No Timescale: Not Specified Funding: Not Specified              |
| Action / Future Plan   |
|  |
| C.3.8 Is the threshold level or flush with surface flooring?               |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/014a Rear pupil entrance                                       |
| Comments   |
| Take out sill  |

| Compliant: No Timescale: Not Specified Funding: Not Specified |
|---|
| Action / Future Plan  |
|   |
| C.3.8 Is the threshold level or flush with surface flooring?  |
| Priority  |
| 2 - As soon as possible                                       |
| Location  |
| Block 1 - 0/018a Pupil entrance                               |
| Comments  |
| Take out timber sill  |
| Compliant: No Timescale: Not Specified Funding: Not Specified |
| Action / Future Plan  |
|   |
| C.3.8 Is the threshold level or flush with surface flooring?  |
| Priority  |
| 2 - As soon as possible                                       |
| Location  |
| Block 3 - 0/004 Yr 4 and 5                                    |
| Comments  |
| Approx 40mm high, provide graded threshold                    |
| Compliant: No Timescale: Not Specified Funding: Not Specified |
| Action / Future Plan  |
|   |
| C.3.9 Is the weather mat of a firm texture?                   |
| Priority  |
| 2 - As soon as possible                                       |
| Location  |
| Block 1 - 0/034 Principal entrance                            |

| Comments   |
|--|
| Consider fitting mat well                                      |
| Compliant: Yes Timescale: Not Specified Funding: Other Funding |
| Action / Future Plan   |
| Removed  |
|  |
| C.3.9 Is the weather mat of a firm texture?                    |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/006c Infant entrance                               |
| Comments   |
| Consider mat well  |
| Compliant: Yes Timescale: Not Specified Funding: Other Funding |
| Action / Future Plan   |
| Removed  |
|  |
| C.3.9 Is the weather mat of a firm texture?                    |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/034 Rear pupil entrance                            |
| Comments   |
| Consider mat well  |
| Compliant: No Timescale: 1-3 Years Funding: Devolved Capital   |
| Action / Future Plan   |
| To be considered when funding available                        |

| C.3.10 Is the weather mat flush with the floor?                |
|--|
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/018a Pupil entrance                                |
| Comments   |
| Mat laid loose on floor, consider mat well                     |
| Compliant: Yes Timescale: Not Specified Funding: Other Funding |
| Action / Future Plan   |
| Removed  |
|  |
| C.5.2 Does the lobby door meet disabled access criteria?       |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/014a Rear pupil entrance                           |
| Comments   |
| Paint door to contrast and replace handle                      |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| C.5.2 Does the lobby door meet disabled access criteria?       |
| Priority   |

| 2 - As soon as possible  Location |  |
|-----------------------------------|--|
| Location                          |  |
|                                   |  |
| Block 3 - 0/004                   |  |
| Comments                          |  |

| Compliant: No Timescale: Not Specified Funding: Not Specified    |
|--|
| Action / Future Plan   |
|  |
| C.5.2 Does the lobby door meet disabled access criteria?         |
| Priority   |
| 4 - Part of Refurbishment work                                   |
| Location   |
| Block 1 - 0/018a Pupil entrance                                  |
| Comments   |
| 630mm wide, replace with door and a half set once ramp is fitted |
| Compliant: Yes Timescale: Not Specified Funding: Other Funding   |
| Action / Future Plan   |
| Both doors can be opened   |
|  |
| C.5.2 Does the lobby door meet disabled access criteria?         |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 2 - 0/002  |
| Comments   |
| Only 730mm wide, increase opening                                |
| Compliant: No Timescale: Not Specified Funding: Not Specified    |
| Action / Future Plan   |
|  |
| C.5.2 Does the lobby door meet disabled access criteria?         |
| Priority   |
| 2 - As soon as possible  |
| Location   |

| Block 1 - 0/006c Infant entrance  |
|---|
| Comments  |
| Recommendations included in internal doors section of report  |
| Compliant: Yes Timescale: Not Specified Funding: Devolved Capital   |
| Action / Future Plan  |
| New door fitted   |
|   |
| <b>C.5.3</b> Is the lobby large enough to allow wheelchair users to clear one door before negotiating the second door?                |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/018a Pupil entrance   |
| Comments  |
| Only 1.66m long, consider enlarging   |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital  |
| Action / Future Plan  |
| To be considered when funding becomes available   |
|   |
| <b>C.5.5</b> Are signs designated and positioned to inform those with visual impairments and wheelchair users with reduced eye level? |
| Priority  |
| 4 - Part of Refurbishment work  |
| Location  |
| Block 2 - 0/002   |
| Comments  |
| Consider sign   |
| Compliant: No Timescale: Not Specified Funding: Not Specified   |
| Action / Future Plan  |

| <b>C.5.5</b> Are signs designated and positioned to inform those with visual impairments and wheelchair users with reduced eye level? |
|---|
| Priority  |
| 4 - Part of Refurbishment work  |
| Location  |
| Block 3 - 0/004   |
| Comments  |
| Consider upgrading  |
| Compliant: No Timescale: Not Specified Funding: Not Specified   |
| Action / Future Plan  |
|   |
| C.5.7 Are floor surfaces slip resistant?  |
| Priority  |
| 3 - Part of Maintenance work  |
| Location  |
| Block 1 - 0/034 Principal entrance  |
| Comments  |
| Carpeted, but fitted weather map required   |
| Compliant: No Timescale: Not Specified Funding: Not Specified   |
| Action / Future Plan  |
|   |
| C.5.7 Are floor surfaces slip resistant?  |
| Priority  |
| 3 - Part of Maintenance work  |
| Location  |
| Block 2 - 0/002   |
| Comments  |
| Carpeted, but fitted weather mat required   |

| Compliant: No Timescale: Not Specified Funding: Not Specified  |
|--|
| Action / Future Plan   |
|  |
| C.5.7 Are floor surfaces slip resistant?                       |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/018a Pupil entrance                                |
| Comments   |
| Tiled floor, provide non-slip finish                           |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| C.5.8 Do hard floor surfaces avoid causing acoustic confusion? |
| Priority   |
| 5 - When a specific need is identified                         |
| Location   |
| Block 1 - 0/034 Principal entrance                             |
| Comments   |
| Due to nature of use   |
| Compliant: No Timescale: Ongoing Funding: Devolved Capital     |
| Action / Future Plan   |
| No need currently  |
|  |
| C.5.8 Do hard floor surfaces avoid causing acoustic confusion? |
| Priority   |
| 5 - When a specific need is identified                         |
| Location   |

| Block 1 - 0/014a Rear pupil entrance                           |
|--|
| Comments   |
| Due to nature of use   |
| Compliant: No Timescale: Ongoing Funding: Devolved Capital     |
| Action / Future Plan   |
| No need currently  |
|  |
| C.5.8 Do hard floor surfaces avoid causing acoustic confusion? |
| Priority   |
| 5 - When a specific need is identified                         |
| Location   |
| Block 3 - 0/004  |
| Comments   |
| Due to nature of use   |
| Compliant: No Timescale: Ongoing Funding: Devolved Capital     |
| Action / Future Plan   |
| No need currently  |
|  |
| C.5.8 Do hard floor surfaces avoid causing acoustic confusion? |
| Priority   |
| 5 - When a specific need is identified                         |
| Location   |
| Block 2 - 0/002  |
| Comments   |
| Due to nature of use   |
| Compliant: No Timescale: Ongoing Funding: Devolved Capital     |
| Action / Future Plan   |

No need currently

| C.5.8 Do hard floor surfaces avoid causing acoustic confusion?  |
|---|
| Priority  |
| 5 - When a specific need is identified  |
| Location  |
| Block 1 - 0/006c Infant entrance  |
| Comments  |
| Due to nature of use  |
| Compliant: No Timescale: Ongoing Funding: Devolved Capital  |
| Action / Future Plan  |
| No need currently   |
|   |
| C.5.8 Do hard floor surfaces avoid causing acoustic confusion?  |
| Priority  |
| 5 - When a specific need is identified  |
| Location  |
| Block 1 - 0/018a Pupil entrance   |
| Comments  |
| Due to nature of use  |
| Compliant: No Timescale: Not Specified Funding: Not Specified   |
| Action / Future Plan  |
|   |
| <b>C.5.10</b> Are junctions between floor surfaces formed to prevent tripping hazards or to cause visual confusion? |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/018a Pupil entrance   |
| Comments  |
| Take out metal strip at inner doors and fit new flush strip   |

| Compliant: No Timescale: Not Specified Funding: Not Specified  |
|--|
| Action / Future Plan   |
|  |
| <b>C.5.10</b> Are junctions between floor surfaces formed to prevent tripping hazards or to cause visual confusion?                          |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/006c Infant entrance   |
| Comments   |
| Fit flush jointing strip between carpet/flooring   |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| <b>C.6.3</b> Are signs designated and located to convey information to visually impaired visitors and wheelchair users with lower eye level? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/035  |
| Comments   |
| Fit sign   |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| C.6.5 Is there an induction loop fitted with signage to identify?  |
| Priority   |
| 2 - As soon as possible  |
| Location   |

| Block 1 - 0/035  |
|--|
| Comments   |
| Fit loop   |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital   |
| Action / Future Plan   |
| To be considered when funding becomes available  |
|  |
| C.6.17 Is there a good mix of seating suitable for all disabilities?   |
| Priority   |
| 3 - Part of Maintenance work   |
| Location   |
| Block 1 - 0/035  |
| Comments   |
| Consider provision of seats with arms  |
| Compliant: Yes Timescale: Not Specified Funding: Other Funding   |
| Action / Future Plan   |
| Seats available  |
|  |
| <b>D.1.2</b> Are corridors, passageways, aisles wide enough for a wheelchair and other people to pass through? |
| Priority   |
| 5 - When a specific need is identified   |
| Location   |
| Block 1 - 0/010a,30,30a  |
| Comments   |
| Sections of some corridors/passageways only 1.1-1.14m wide,  |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital   |
| Action / Future Plan   |
| To be considered when funding becomes available  |

| <b>D.1.3</b> Are the corridors free from obstructions and hazards for both wheelchair users and people with impaired vision? |
|--|
| Priority   |
| 3 - Part of Maintenance work   |
| Location   |
| Block 1 - 0/010a,30,30a  |
| Comments   |
| Consider repositioning certain item stored in corridors to free them   |
| Compliant: Yes Timescale: Not Specified Funding: Other Funding   |
| Action / Future Plan   |
| Repositioning achieved   |
|  |
| D.1.9 Are tactile signs available for use by people with impaired vision?  |
| Priority   |
| 4 - Part of Refurbishment work   |
| Location   |
| Block 1 - 0/006b,10a,18,28,30,30a,40   |
| Comments   |
| Consider upgrading signage   |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| D.1.11 Are floor surfaces slip resistant?  |
| Priority   |
| 4 - Part of Refurbishment work   |
| Location   |
| Block 1 - 0/006b,10a,30a   |
| Comments   |
| •  |

| Some corridors have either a tiled floor or timber floor, provide non slip finish |
|---|
| Compliant: No Timescale: Not Specified Funding: Not Specified                     |
| Action / Future Plan  |
|   |
| D.1.12 Do hard floor surfaces avoid causing acoustic confusion?                   |
| Priority  |
| 5 - When a specific need is identified  |
| Location  |
| Block 1 - 0/006b,10a,30a  |
| Comments  |
| Due to nature of use  |
| Compliant: No Timescale: Ongoing Funding: Devolved Capital                        |
| Action / Future Plan  |
| No current need   |
|   |
| D.1.15 Are textured surfaces used to convey information?                          |
| Priority  |
| 3 - Part of Maintenance work  |
| Location  |
| Block 1 - 0/006b,10a,28,30,30a,40   |
| Comments  |
| Consider provision when replacing flooring  |
| Compliant: No Timescale: Not Specified Funding: Not Specified                     |
| Action / Future Plan  |
|   |
| D.3.4 Are floor surfaces slip resistant?  |
| Priority  |
| 4 - Part of Refurbishment work  |

| Location  |
|---|
| Location  |
| Block 1 - 0/014 Hall  |
| Comments  |
| Timber floor, provide non-slip finish   |
| Compliant: No Timescale: Not Specified Funding: Not Specified                                       |
| Action / Future Plan  |
|   |
| D.3.4 Are floor surfaces slip resistant?  |
| Priority  |
| 4 - Part of Refurbishment work  |
| Location  |
| Block 1 - 0/001,4,23,30b,31   |
| Comments  |
| Classrooms - part timber floor, small computer area - tiled floor, provide non-slip finish in each. |
| Compliant: No Timescale: Not Specified Funding: Not Specified                                       |
| Action / Future Plan  |
|   |
| D.3.5 Do floor surfaces avoid causing acoustic confusion?   |
| Priority  |
| 5 - When a specific need is identifie   |
|   |
| Location  |
| Block 1 - 0/014 Hall  |
|   |
| Block 1 - 0/014 Hall  |
| Block 1 - 0/014 Hall  Comments  |
| Block 1 - 0/014 Hall  Comments  Due to nature of use  |

| D.3.5 Do floor surfaces avoid causing acoustic confusion?  |
|--|
| Priority   |
| 5 - When a specific need is identified                     |
| Location   |
| Block 2 - 0/001 Yr 6 classroom                             |
| Comments   |
| Due to nature of use                                       |
| Compliant: No Timescale: Ongoing Funding: Devolved Capital |
| Action / Future Plan                                       |
| No current need  |
|  |
| D.3.5 Do floor surfaces avoid causing acoustic confusion?  |
| Priority   |
| 5 - When a specific need is identified                     |
| Location   |
| Block 3 - 0/001,3, Yr 4 and 5 classrooms                   |
| Comments   |
| Due to nature use  |
| Compliant: No Timescale: Ongoing Funding: Devolved Capital |
| Action / Future Plan                                       |
| No current need  |
|  |
| D.3.5 Do floor surfaces avoid causing acoustic confusion?  |
| Priority   |
| 5 - When a specific need is identified                     |
| Location   |

Block 1 - Classrooms, practical, ICT, staffroom

Comments

| Due to nature of use   |
|--|
| Compliant: No Timescale: Ongoing Funding: Devolved Capital                     |
| Action / Future Plan   |
| No current need  |
|  |
| D.3.9 Is there adequate signage including means of escape?                     |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/004,33   |
| Comments   |
| Fit escape signage   |
| Compliant: No Timescale: Within 12 Months Funding: Other Funding               |
| Action / Future Plan   |
| New Signs to be fitted   |
|  |
| D.3.12 Are all areas for assembly equipped with an induction loop and signage? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 2 - 0/001 Yr 6 classroom   |
| Comments   |
| Included in block 1  |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital                   |
| Action / Future Plan   |
| To be considered as soon as funding becomes available                          |

**D.3.12** Are all areas for assembly equipped with an induction loop and signage?

| Priority   |
|--|
| 2 - As soon as possible  |
| Location   |
| Block 1 - Classrooms, ICT, staffroom, offices                                  |
| Comments   |
| Provide portable loop  |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital                   |
| Action / Future Plan   |
| To be considered as soon as funding becomes available                          |
|  |
| D.3.12 Are all areas for assembly equipped with an induction loop and signage? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 3 - 0/001,3, Yr 4 and 5 classrms   |
| Comments   |
| Included in block 1  |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital                   |
| Action / Future Plan   |
| To be considered as soon as funding becomes available                          |
|  |
| D.3.12 Are all areas for assembly equipped with an induction loop and signage? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/014 Hall   |
| Comments   |
| Fit loop   |

| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital                      |
|---|
| Action / Future Plan  |
| To be considered as soon as funding becomes available                             |
|   |
| D.3.13 If use of an induction loop is precluded is an infra red system available? |
| Priority  |
| 3 - Part of Maintenance work  |
| Location  |
| Block 1 - 0/014 Hall  |
| Comments  |
| Consider as an alternative to loop system   |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital                      |
| Action / Future Plan  |
| To be considered as soon as funding becomes available                             |
|   |
| D.3.13 If use of an induction loop is precluded is an infra red system available? |
| Priority  |
| 3 - Part of Maintenance work  |
| Location  |
| Block 1 - Classrooms, ICT, staffroom, offices                                     |
| Comments  |
| Consider provision for confidentiality in Heads office                            |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital                      |
| Action / Future Plan  |
| To be considered as soon as funding becomes available                             |
|   |
| F.1.2 Does the door and door furniture comply with BS8300?                        |
| Priority  |

| 4 - Part of Refurbishment work                                |
|---|
| Location  |
| Block 1 - None Given  |
| Comments  |
| See recommendations below                                     |
| Compliant: No Timescale: Not Specified Funding: Not Specified |
| Action / Future Plan  |
|   |
| F.1.2 Does the door and door furniture comply with BS8300?    |
| Priority  |
| 2 - As soon as possible                                       |
| Location  |
| Block 2 - 0/004   |
| Comments  |
| Replace door handle   |
| Compliant: No Timescale: Not Specified Funding: Not Specified |
| Action / Future Plan  |
|   |
| F.1.2 Does the door and door furniture comply with BS8300?    |
| Priority  |
| 2 - As soon as possible                                       |
| Location  |
| Block 3 - 0/004a  |
| Comments  |
| Replace handle  |
| Compliant: No Timescale: Not Specified Funding: Not Specified |
| Action / Future Plan  |

| F.1.3 Are the internal doors easily distinguishable from their surroundings?   |
|--|
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/015  |
| Comments   |
| Paint door   |
| Compliant: No Timescale: Not Specified Funding: Not Specified                  |
| Action / Future Plan   |
|  |
| F.1.5 Can people on both sides of the door see each other and be clearly seen? |
| Priority   |

| Tino Can po    | ppio on both cideo of       | 4001 000 04011            | ther and be clearly seen? |  |
|----------------|-----------------------------|---------------------------|---------------------------|--|
| Priority       |                             |                           |                           |  |
| 2 - As soon a  | s possible                  |                           |                           |  |
| Location       |                             |                           |                           |  |
| Block 1 - 0/01 | 7,19                        |                           |                           |  |
| Comments       |                             |                           |                           |  |
| Fit vision pan | els                         |                           |                           |  |
| Compliant: N   | o <b>Timescale</b> : Not Sp | ecified <b>Funding:</b> N | ot Specified              |  |
| Action / Futu  | re Plan                     |                           |                           |  |

| F.1.6 Is the opening of the door a sufficient width for wheelchair use? |  |
|---|--|
| Priority  |  |
| 4 - Part of Refurbishment work  |  |
| Location  |  |
| Block 1 - 0/002,3,17,19,27,29,2x9b,3x14                                 |  |
| Comments  |  |
| 620-720mm wide, replace 3No double door sets and increase 8No openings  |  |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital            |  |

| To be considered as soon as funding becomes available                                  |
|--|
|  |
| F.1.10 Are the controls easily gripped and operated?                                   |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - Where required   |
| Comments   |
| Replace 14No   |
| Compliant: No Timescale: Not Specified Funding: Not Specified                          |
| Action / Future Plan   |
|  |
| G.1.2 Is the lobby of sufficient size for easy access?                                 |
| Priority   |
| 5 - When a specific need is identifie  |
| Location   |
| Block 1 - 0/016 Male staff   |
| Comments   |
| Lobby only 820mm wide  |
| Compliant: No Timescale: Not Specified Funding: Not Specified                          |
| Action / Future Plan   |
|  |
| G.1.4 Is the approach to the cubicle free of steps, narrow corridors and obstructions? |
| Priority   |
| 5 - When a specific need is identifie  |
| Location   |
| Block 1 - 0/021 Female staff   |

Action / Future Plan

| Comments   |
|--|
| Passage between walls before entering door to WC only 590mm wide. Disabled WC provided elsewhere |
| Compliant: No Timescale: Not Specified Funding: Not Specified                                    |
| Action / Future Plan   |
|  |
| G.1.4 Is the approach to the cubicle free of steps, narrow corridors and obstructions?           |
| Priority   |
| 5 - When a specific need is identified   |
| Location   |
| Block 1 - 0/016 Male staff   |
| Comments   |
| Wall to radiator shelf only 715mm wide, consider removal   |
| Compliant: No Timescale: Not Specified Funding: Not Specified                                    |
| Action / Future Plan   |
|  |
| G.1.6 Are all fittings readily distinguishable from their background?                            |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/009b Kitchen staff   |
| Comments   |
| Replace wall tiling and redecorate walls at fittings to provide contrast                         |
| Compliant: Yes Timescale: Ongoing Funding: Devolved Capital                                      |
| Action / Future Plan   |
| Newly painted and tiled  |
|  |

**G.1.6** Are all fittings readily distinguishable from their background?

| Priority  |
|---|
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/002 girls, 0/003 Boys Infant                              |
| Comments  |
| Redecorate walls to provide contrast with fittings in each toilet     |
| Compliant: Yes Timescale: Not Specified Funding: Devolved Capital     |
| Action / Future Plan  |
| Newly painted and tiled   |
|   |
| G.1.6 Are all fittings readily distinguishable from their background? |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/016 Male staff  |
| Comments  |
| Replace tiling to contrast and redecorate walls to provide contrast   |
| Compliant: Yes Timescale: Not Specified Funding: Devolved Capital     |
| Action / Future Plan  |
| Newly painted and tiled   |
|   |
| G.1.6 Are all fittings readily distinguishable from their background? |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/027 Girls, 0/029 Boys                                     |
| Comments  |
| Replace tiling and redecorate walls at fittings to provide contrast   |

| Compliant: Yes Timescale: Not Specified Funding: Devolved Capital     |
|---|
| Action / Future Plan  |
| Newly painted and tiled   |
|   |
| G.1.6 Are all fittings readily distinguishable from their background? |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/021 Female staff  |
| Comments  |
| Replace tiling to contrast at wash hand basin                         |
| Compliant: Yes Timescale: Ongoing Funding: Devolved Capital           |
| Action / Future Plan  |
| Newly painted and tiled   |
|   |
| G.1.7 Are the compartment door controls easily gripped and operated?  |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/009b Kitchen staff  |
| Comments  |
| Replace   |
| Compliant: No Timescale: Not Specified Funding: Not Specified         |
| Action / Future Plan  |
|   |
| G.1.7 Are the compartment door controls easily gripped and operated?  |
| Priority  |
| 2 - As soon as possible   |

| Location  |
|---|
| Block 1 - 0/016 Male staff  |
| Comments  |
| Replace   |
| Compliant: No Timescale: Not Specified Funding: Not Specified                   |
| Action / Future Plan  |
|   |
| G.1.7 Are the compartment door controls easily gripped and operated?            |
| Priority  |
| 3 - Part of Maintenance work  |
| Location  |
| Block 1 - 0/002 girls, 0/003 Boys Infant  |
| Comments  |
| Consider removal of all controls as they are not required in the infant toilets |
| Compliant: Yes Timescale: Not Specified Funding: Devolved Capital               |
| Action / Future Plan  |
| New Fittings  |
|   |
| G.1.7 Are the compartment door controls easily gripped and operated?            |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/027 Girls, 0/029 Boys   |
| Comments  |
| Replace 4No in girls and 2No in boys  |
| Compliant: Yes Timescale: Not Specified Funding: Devolved Capital               |
| Action / Future Plan  |
| New Fittings  |

| G.1.7 Are the compartment door controls easily gripped and operated?                                     |
|--|
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/021 Female staff   |
| Comments   |
| Replace  |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| <b>G.1.8</b> Can ambulant disabled people manoeuvre and rise and lower themselves in a standard cubicle? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/009b Kitchen staff   |
| Comments   |
| Fit grab rails   |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| <b>G.1.8</b> Can ambulant disabled people manoeuvre and rise and lower themselves in a standard cubicle? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/027 Girls, 0/029 Boys  |
| Comments   |
| Fit a set of grab rails in each toilet   |

| Compliant: No Timescale: Not Specified Funding: Not Specified  |
|--|
| Action / Future Plan   |
|  |
| <b>G.1.8</b> Can ambulant disabled people manoeuvre and rise and lower themselves in a standard cubicle? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/002 girls, 0/003 Boys Infant   |
| Comments   |
| Fit a set of grab rails in the girls toilet and an additional grab rail in the boys                      |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| <b>G.1.8</b> Can ambulant disabled people manoeuvre and rise and lower themselves in a standard cubicle? |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/016 Male staff   |
| Comments   |
| Fit grab rails   |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| <b>G.1.8</b> Can ambulant disabled people manoeuvre and rise and lower themselves in a standard cubicle? |
| Priority   |
| 2 - As soon as possible  |

| Location   |
|--|
| Block 1 - 0/021 Female staff   |
| Comments   |
| Fit grab rails   |
| Compliant: No Timescale: Not Specified Funding: Not Specified              |
| Action / Future Plan   |
|  |
| G.1.9 Do the floors have a slip resistant finish?                          |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/009b Kitchen staff   |
| Comments   |
| Tiled floor, provide non slip finish                                       |
| Compliant: No Timescale: Not Specified Funding: Not Specified              |
| Action / Future Plan   |
|  |
| G.1.9 Do the floors have a slip resistant finish?                          |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/021 Female staff   |
| Comments   |
| Tiled floor, provide non-slip finish                                       |
| Compliant: Yes Timescale: Not Specified Funding: Access Initiative Funding |
| Action / Future Plan   |
| New Floor  |

| G.1.9 Do the floors have a slip resistant finish?                 |
|---|
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/002 girls, 0/003 Boys Infant                          |
| Comments  |
| Tiled floors, provide non-slip finish in each toilet              |
| Compliant: Yes Timescale: Not Specified Funding: Devolved Capital |
| Action / Future Plan  |
| New Floor   |
|   |
| <b>G.1.9</b> Do the floors have a slip resistant finish?          |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/016 Male staff  |
| Comments  |
| Tiled floor, provide non-slip finish                              |
| Compliant: Yes Timescale: Not Specified Funding: Devolved Capital |
| Action / Future Plan  |
| New Floor   |
|   |
| G.1.9 Do the floors have a slip resistant finish?                 |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 1 - 0/027 Girls, 0/029 Boys                                 |
| Comments  |

| Both have tiled floors, provide non slip finish in each toilet                                       |
|--|
| Compliant: Yes Timescale: Not Specified Funding: Devolved Capital                                    |
| Action / Future Plan   |
| New Floor  |
|  |
| G.2.4 Is it a corner layout?   |
| Priority   |
| 4 - Part of Refurbishment work   |
| Location   |
| Block 1 - 0/028a   |
| Comments   |
| Only 2 m x 1.5m wide, reposition existing and fit new to comply with corner layout, see exec summary |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| G.2.20 Can the door be opened with ease and be opened outwards in an emergency?                      |
| Priority   |
| 2 - As soon as possible  |
| Location   |
| Block 1 - 0/028a   |
| Comments   |
| Re-hang door to open outwards, corridor 1.5m wide  |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| H.1.2 Is provision provided on both sides for wheelchair users?                                      |

Priority

| 3 - Part of Maintenance work   |
|--|
| Location   |
| Block 0 - 0/009  |
| Comments   |
| 870mm high, consider alterations   |
| Compliant: No Timescale: Not Specified Funding: Not Specified  |
| Action / Future Plan   |
|  |
| <b>H.4.5</b> Is the lighting in the workspace controllable and adjustable to meet the needs of the individual and the task that they are working on? |
| Priority   |
| 3 - Part of Maintenance work   |
| Location   |
| Block 0 - None Given   |
| Comments   |
| Consider provision if the need arises  |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital   |
| Action / Future Plan   |
| No current need  |
|  |
| I.1.2 Is the kitchen provided with fittings suitable for use by people with disabilities?  |
| Priority   |
| 3 - Part of Maintenance work   |
| Location   |
| Block 1 - 0/009 Staff kitchen  |
| Comments   |
| Consider provision when the need arises  |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital   |
| Action / Future Plan   |
| .1   |


| I.1.2 Is the kitchen provided with fittings suitable for use by people with disabilities? |
|---|
| Priority  |
| 3 - Part of Maintenance work  |
| Location  |
| Block 1 - 0/033 Staffroom   |
| Comments  |
| Consider provision if the need arises   |
| Compliant: No Timescale: Ongoing Funding: Devolved Capital                                |
| Action / Future Plan  |
| No current need   |
|   |
| K.1.1 Is the audible alarm supplemented by a visual system?                               |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 0 - All buildings   |
| Comments  |
| Fit visual alarms eg xenon beacons to existing audible fire alarm system                  |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital                              |
| Action / Future Plan  |
|   |
| To be considered when funding becomes available   |
|   |
| K.1.2 Are ground floor exit routes as accessible as entrance routes?                      |
| Priority  |
| 1 - Immediate/Urgent work   |
| Location  |

No current need

| Block 0 - B1-0/004,9,33,37,B3-0/001,3   |
|---|
| Comments  |
| Upgrade fire exits and fit ramps and extend path where required   |
| Compliant: No Timescale: Not Specified Funding: Not Specified   |
| Action / Future Plan  |
|   |
| <b>K.1.6</b> Is there a personal egress plan in place for any member of staff who may require assistance? |
| Priority  |
| 4 - Part of Refurbishment work  |
| Location  |
| Block 0 - None Given  |
| Comments  |
| Consult fire professional and put plan in place   |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital  |
| Action / Future Plan  |
| No current need   |
|   |
| K.1.7 Is fire exit signage and signs to places of safety within the building adequate?                    |
| Priority  |
| 2 - As soon as possible   |
| Location  |
| Block 0 - None Given  |
| Comments  |
| Included elsewhere  |
| Compliant: No Timescale: Not Specified Funding: Not Specified   |
| Action / Future Plan  |
|   |

M.1.10 Is flooring replaced on a like for like basis?

| Priority   |
|--|
| 2 - As soon as possible                                      |
| Location   |
| Block 0 - None Given   |
| Comments   |
| It is improved   |
| Compliant: No Timescale: 3-6 Years Funding: Devolved Capital |
| Action / Future Plan   |
| Planned as programme develops                                |



### Accessibility Action Plan - Access to the Curriculum

### Curriculum ID: 1

### Question

Do you ensure that teachers and teaching assistants have the necessary training to teach and support pupils with disabilities?

Yes - Timescale: Ongoing Funding: Other Funding

### Details / Future Plan

When notification is given appropriate training is arranged through the Local Authority. We update all training as required.

### Curriculum ID: 2

### Question

Are your classrooms optimally organised for disabled pupils?

Yes - Timescale: Ongoing Funding: Other Funding

### **Details / Future Plan**

Within the constraints of the building all classrooms are optimally organised and adaptations to layout, signage and furniture are adjusted according to the needs of all pupils. Equipment is provided as necessary. Specialist teachers are consulted frequently and management plans are created to support all staff.

### Curriculum ID: 3

### Question

Do lessons provide opportunities for all pupils to achieve?

Yes - Timescale: Not Specified Funding: Not Specified

### Details / Future Plan

Teachers are aware of all children's needs within the school. Frequent staff meetings and PD sessions give advice and support on teaching and learning strategies. The SENCO works with colleagues to ensure that appropriate methodologies are used and the Headteacher monitors practice.

### Curriculum ID: 4

### Question

Are all pupils encouraged to take part in music, drama and physical activities?

Yes - Timescale: Ongoing Funding: Other Funding

### Details / Future Plan

We have Active Mark Gold and Arts Mark Silver. These are external audits which assess our childrens involvement in these areas of the curriculum. The last OfSTED report recognised our strength in these areas.

### **Curriculum ID: 5**

### Question

Do staff recognise and allow for the considerable effort expended by some pupils with disabilities, to access the curriculum?

Yes - Timescale: Ongoing Funding: Other Funding

### Details / Future Plan

The staff are well aware and issues are shared in staff meetings etc. PD is always available for staff and they are well supported by the SENCO and our experienced team of SSS.

### Curriculum ID: 6

### Question

Do staff recognise and allow for the additional time required by some pupils with disabilities, to use equipment in practical work?

Yes - Timescale: Ongoing Funding: Other Funding

### Details / Future Plan

All staff are aware of this issue and take practical steps to ensure that any difficulties are overcome.

### Curriculum ID: 7

### Question

Have you considered the impact of the timetable on pupils with disabilities?

Yes - Timescale: Ongoing Funding: Other Funding

### Details / Future Plan

Reasonable adjustments are made to the timetable to minimise this impact.

### **Curriculum ID: 8**

### Question

Is provision made for pupils with disabilities who cannot engage in particular activities?

Yes - Timescale: Ongoing Funding: Other Funding

### Details / Future Plan

Alternatives are offered and advice is sought from our local Special School, the LEA and our SENCO. All pupil needs are considered and adaptations made.

### Curriculum ID: 9

### Question

Do you provide a range of I.C.T. access aids and adaptations?

Yes - Timescale: Ongoing Funding: Devolved Capital

### Details / Future Plan

These are used when required after advice has been sought from the LA specialist team, our SENCO and others.

### Curriculum ID: 10

### Question

Do all pupils have access to the wider curriculum including extra-curricular activities?

Yes - Timescale: Ongoing Funding: Other Funding


### Details / Future Plan

We offer all pupils access to school excursions, clubs, activities etc. Particular activities are designed for certain pupils to give them better access or access to more appropriate activities e.g. Tai Chi, New Age Curling etc. No pupil is denied access to any activity if at all possible; activities are specifically designed to involve all. Adjustments are always made to activities to include all pupils.

### **Curriculum ID: 11**

| Question   |  |
|--|--|
| Are there high expectations of all pupils?   |  |
| Yes - Timescale: Not Specified Funding: Not Specified  |  |
| Details / Future Plan  |  |
| Work is carefully differentiated, appropriate targets are set and challenge is present for all our |  |

children.



### Accessibility Action Plan - Access to Information

# Information ID: 1 Question Do you provide information in simple language, symbols, large print, on audiotape or in Braille for pupils and prospective pupils who may have difficulty with standard forms of printed information? Yes - Timescale: Ongoing Funding: Other Funding Details / Future Plan When appropriate this is organised.

### Information ID: 2

### Question

Do you ensure that information is presented to groups in a way, which is user friendly for people with disabilities e.g. by reading aloud overhead projections and describing diagrams?

Yes - Timescale: Ongoing Funding: Other Funding

### **Details / Future Plan**

When appropriate this is organised. There are generally a number of approaches and options available to children during lessons.

### Information ID: 3


### Question

Do you have the facilities such as ICT to produce written information in different formats?

Yes - Timescale: Ongoing Funding: Devolved Capital

### Details / Future Plan

A wide range of appropriate equipment.




# Management

- (i) The Headteacher will coordinate the gathering and input of information into the database. This will be an on-going process. The planning group will meet regularly in order to provide updates on the progress and implementation of the plan.
- (ii) As an agenda item of their Governing Body meeting Governors will begin to understand that it is their key responsibility to have a current school's access plan in place and identify priorities within their responsibilities. Governors will be kept up-to-date and will monitor and evaluate any changes against the plan on a termly basis.
- (iii) The school will review and revise its plan on a regular basis following the planning group meeting.
- (iv) As an agenda item of staff meetings we will be able to offer/provide staff development and training to ensure that all staff are aware of the DDA duties as they apply to the school and also to secure the commitment of staff to removing barriers and increasing access and identify any specific training needs. The Accessibility Plan will be embedded in the School's Improvement Plan (SIP), SEN Plan, Staff Development Programme and Curriculum Planning Programme. Findings relating to this item will be circulated to Governors to enable them to carry out their evaluation and monitoring role.
- (v) Aspects of DDA will be highlighted to the pupils, during SEAL and PHSCE and once a year the school council will be asked to complete a survey on their views on whether they think that the school has become more accessible to all. The results of this survey will be feedback to the Governors to enable them to carry out their evaluation and monitoring role.
- (vi) As an agenda item of every cluster group meeting we will be able to share good practice, ideas and information with other schools. Once estimates of costs are received regarding any relevant works these will be considered by the Finance Committee and reported to the full Governing Body meeting. Governors will then determine the priority and source of appropriate finance.

## Circulation

- (i) The School's Accessibility Plan is available in school stored in the meeting room. Any interested parties should contact the Headteacher in the first instance to view the Plan. The Plan will be available in an easy to read paper copy format. This information will be communicated via the School Profile\*, which is updated annually for parents, and any interested parties who should request a copy. A feedback/survey form on the back of the School Profile and also on the school's website will be available for comments from parents. Any comments will be fed back to Governors to enable them to carry out their evaluation and monitoring role.
- (ii) The indication and expected outcomes/performance criteria and timescales are all highlighted within the plan and this will be reported back to parents as part of the consultation process.

In 2005, the Government changed the requirements placed upon Governors for informing parents and the wider community about the way in which the school is working. This is called the School Profile and it replaces the Governors' Annual Report to Parents or AMP. The School Profile includes aspects such as staffing, curriculum, the Board of Governors, the latest OfSTED report summary and SAT results. The School Profile must make parents (and any interested parties) aware of who to contact and/or where to find the School's Accessibility Plan.



# **Durham County Council Accessible Building Audit** Copy available in School